COMMENT SET 1: JAY CAROLL/J. TICHNER

```
Received: from (web36804.mail.mud.yahoo.com [209.191.85.55]) by thor.slc.ca.gov with smtp
        id 677c_82bb4704_db84_11dd_95f8_001372613b8d;
        Mon, 05 Jan 2009 15:56:46 -0800
Received: from thor.slc.ca.gov ([10.105.1.1])
        by rattler1.slc.ca.gov
        for <mcfarls@slc.ca.gov>; Mon, 05 Jan 2009 16:13:59 -0800
Received: from web36804.mail.mud.yahoo.com ([209.191.85.55])
        by rattler1.slc.ca.gov
        for <mcfarls@slc.ca.gov>; Mon, 05 Jan 2009 16:13:58 -0800
Received: from [66.122.78.5] by web36804.mail.mud.yahoo.com via HTTP; Mon, 05 Jan 2009 16:20:01 PST
Received: (qmail 72779 invoked by uid 60001); 6 Jan 2009 00:20:01 -0000
Received: from thor.slc.ca.gov (rattler.slc.ca.gov [134.186.50.194])
        by sa-trinity.slc.ca.gov with SMTP; Mon, 05 Jan 2009 16:20:12 -0800
Return-Path: <macro2953@yahoo.com>
Reply-To: <macro2953@yahoo.com>
From: "Jay Carroll" <macro2953@yahoo.com>
To: <mcfarls@slc.ca.gov>
Subject: ATT Gateway DEIR
Date: Mon, 5 Jan 2009 16:20:01 -0800
Message-ID: <726604.72060.qm@web36804.mail.mud.yahoo.com>
MIME-Version: 1.0
Content-Type: multipart/alternative;
        boundary="----=_NextPart_000_00D3_01C97AEA.6A831040"
X-Mailer: YahooMailWebService/0.7.260.1
Thread-Index: AclvllogzwqQ/penT0Kz6I9fSC3itA==
X-MimeOLE: Produced By Microsoft MimeOLE V6.00.2900.3350

This is a multi-part message in MIME format.

------=_NextPart_000_00D3_01C97AEA.6A831040
Content-Type: text/plain;
        charset="iso-8859-1"
Content-Transfer-Encoding: 7bit
```

I would suggest that you ask ATT to require their contractors to do a better job of proof reading their reports. A quick look at the ROV biological survey report (Appendix F - Part 6) reveals the use of a "multi-bean side scan sonar", and the presence of the "aggravated vase sponge". There are other spelling, format, and punctuation errors too numerous to mention. This reflects poorly on the quality of the work itself, which one assumes was performed to high standards.

1-1

J. Tichner, Los Osos, CA

```
------=_NextPart_000_00D3_01C97AEA.6A831040
Content-Type: text/html;
        charset="iso-8859-1"
Content-Transfer-Encoding: quoted-printable

<table cellspacing=3D"0" cellpadding=3D"0" border=3D"0" ><tr><td =
valign=3D"top" style=3D"font: inherit;"><DIV>I would suggest that you =
ask ATT to require their contractors to do a better job of proof reading =
their reports. A quick look at the ROV biological survey report =
(Appendix F - Part 6) reveals the use of a "multi-bean side scan sonar", =
and the presence of the "aggravated vase sponge". There are other =
spelling, format, and punctuation errors too numerous to mention. This =
reflects poorly on the quality of the work itself, which one assumes was =
performed to high standards.</DIV>
<DIV> </DIV>
<DIV>J. Tichner, Los Osos, CA</DIV></td></tr></table><br>

------=_NextPart_000_00D3_01C97AEA.6A831040--
```

1

1 **RESPONSE TO COMMENT SET 1: JAY CAROLL/J. TICHNER**

2 1-1 The comment presents a general concern about typographic errors in the
3 ROV Biological Survey Report (Appendix F of the DEIR). No response is
4 required, but the comment is included for consideration by the decision-
5 makers.